




# Installation Instruction



# Assembling

Estimated time for assembly




45 : 00

# What' included

| Code Description  | Qty |
|-------------------|-----|
| A Screw M3.5X14MM | 42  |

## What you need

- Use the packaging carton as a working surface to prevent product damage during assembly
- Phillips head screwdriver




## Weight Limitation



100 | 35

lbs table top    lbs per



# The Hardwares



## **IMPORTANT:**


- 1.Do not tighten bolts / screws completely until all bolts / screws are lined up and inserted into holes.
- 2.Do not over tighten screws and bolts to avoid stripping
- 3.Please use hand tools to assemble this product. Do not use power tools.

# Included Accessories


---

| Code | Description                 | Qty |
|------|-----------------------------|-----|
| 1    | Great circle panel          | 1   |
| 2    | Great circle base plate     | 1   |
| 3    | Small circular panel        | 1   |
| 4    | Round bottom plate          | 1   |
| 5    | Large round side frame      | 1   |
| 6    | Large round support feet    | 4   |
| 7    | Small round side frame      | 1   |
| 8    | Small round supporting feet | 4   |


# The Accessoriess




Step 1




Step 2





# Step 3

|   |     |
|---|-----|
| A   | x 6 |
|  |     |






# Step 4


|   |      |
|---|------|
| A   | x 16 |
|  |      |




# Step 5





# Step 6

|   |     |
|---|-----|
| A   | x 4 |
|  |     |



# Step 7

|   |      |
|---|------|
| A   | x 16 |
|  |      |



# Step 8

