

# **ASSEMBLY INSTRUCTION**

THANK YOU FOR PURCHASING THIS QUALITY PRODUCT BE SURE TO CHECK ALL PACKING MATERIAL CAREFULLY FOR SMALL PARTS THAT MAY HAVE COME LOOSE INSIDE THE CARTON DURING TRANSIT.

#### THIS CART REQUIRES 2 PEOPLE TO ASSEMBLE.



STEP2:MAKE SURE TO PRESS ACRYLIC POLES EVENLY INTO THE BASE FRAME, AND ALL THE TAPERED ACRYLIC ENDS SHOULD BE SUNK INTO THE BASE FRAME. SCREW



### **PART LIST**

| NO | DESC           | SIZE<br>(MM) | SKETCH | QTY  |  |  |  |
|----|----------------|--------------|--------|------|--|--|--|
| Α  | LEG            | Ø40*690      | -      | 4 PC |  |  |  |
| В  | TOP FRAME      | 770*402*47   |        | 1 PC |  |  |  |
| С  | BASE FRAME     | 770*402*220  |        | 1 PC |  |  |  |
| D  | TOP GLASS      | 640*352*10   | **     | 1 PC |  |  |  |
| Е  | BOTTOM MIRROR  | 640*352*10   |        | 1 PC |  |  |  |
| F  | HANDLE FRAME-L | 110*125*47   |        | 1 PC |  |  |  |
| G  | HANDLE FRAME-R | 110*125*47   | A      | 1 PC |  |  |  |
| Н  | HANDLE         | Ø40*396      | A A    | 1 PC |  |  |  |

# HARDWARE LIST

| NO | DESC                | SIZE<br>(MM) | SKETCH | QTY  |
|----|---------------------|--------------|--------|------|
| а  | castor<br>w/ break  | Ø2"*50*m8    |        | 2 PC |
| b  | screw               | m6*35        |        | 2 PC |
| С  | allenkey            | m6*50        | ١      | 1 PC |
| d  | wrench              | m8*50        | S)     | 1 PC |
| е  | castor<br>w/o break | Ø2"*50*m8    |        | 2 PC |

pages: 1/2

# **ASSEMBLY INSTRUCTION**

