






































ASSEMBLY INSRTRUCTION










			
① x 1	② x 1	③ x 1	④ x 1
			
⑤ x 1	⑥ x 1	⑦ x 1	⑧ x 1
			
⑨ x 2	⑩ x 2	⑪ x 1	⑫ x 2
			
⑬ x 2	⑭ x 2	⑮ x 3	⑯ x 4
			
⑰ x 4	⑱ x 4	⑲ x 4	⑳ x 4
			
㉑ x 4	㉒ x 1		

		 Φ 6x30mm	 Φ 4x35mm
A x56+2	B x56+2	C x22+1	D x22+1
 Φ 4x16mm			 Φ 4x12mm
E x6	F x6	G x2	H x2
	 Φ 4x25mm		 Φ 3x14mm
I x2	J x10+1	K x16+1	L x16+1
	 Φ 4x14mm		 Φ 3.5x12mm
M x4	N x24+1	O x8+1	P x32+1
			
CLx4	CRx4	DRx4	DLx4



Step 1






Step 2




Step 3




Step 4




Step 5




Step 6




Step 7






Step 8





Step 9






Step 10





Step 11







Step 12








Step 13






Step 14





Step 15









Step 16




Step 17





Step 18



Φ 4x14mm
Nx16




Step 19







x4

Step 20





x4

Step 21



x4



Step 22




Bx16

x4


Step 23




Bx4



Φ 3.5x12mm
P x16






DRx4



DL x4

x4

Step 25



Step 26

