




① x2




② x2




③ x2




④ x2




⑤ x1




⑥ x1



⑦ x1



⑧ x1



⑨ x1



M6x80

Ax8



Bx8



M6x38

Cx8



Ø12x10

Dx8



M6x25

Ex16




M4x10

Fx18




M4x20


Gx8




Hx3



Ix2




1




x2

2




x2

3




x2


4




5




6




7



8



9



10

