




ASSEMBLY INSTRUCTION



A x2pcs




B × 1 pc



C x1pc



D x4pcs




E x2pcs



+Spare×2



F ×10pcs
M8*16mm

$$+ \text{Spare} \times 2$$



G×10pcs
M8*16mm

$$+ \text{Spare} \times 2$$


H×10pcs
M8*16mm


$$+ \text{Spare} \times 2$$


1x10pcs
ø8/ø16x2mm




Jx1pc
#5


STEP:1



STEP:2




STEP:3




x2


STEP:4



ASSEMBLY INSTRUCTION




+Spare×1




Lx1pc


STEP:5



STEP:6



STEP:7



STEP:8

