


# Assembly Instructions



# BEFORE STARTING

## Before Using Product

Read each step carefully before starting. It is very important that each step is performed in the correct order. If these steps are not followed in sequence, assembly difficulties will occur.

Make sure all parts are included.

Work in a spacious area and near where the unit will be used, preferably on a carpet, or use a piece of the cardboard packaging to protect your floor and product.

For a smooth assembly process, we suggest you keep a lite tightness for all the screws during assembly. After the whole product is assembled, firmly tighten all the screws.

## **WARNING**

Do not allow children to climb on unit.

Avoid sharp objects or corrosive chemicals to prevent damage to the product.

During assembly, keep parts and packaging materials away from children and pets as there could be potential injury and choking hazards.


Please make sure that all objects are removed before moving the assembled unit.

The unit must be team lifted, not dragged or pushed. Failure to do so could cause instability, product collapse, and/or serious injury.







Be careful when using power tools to assemble your furniture.

Power tools may strip or damage the parts.









# PART LIST



# PART LIST

|                                                                                                                         |                                                                                                                         |                                                                                                                           |
|-------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------------------|
| <p><b>1</b></p>  <p><b>1 pc</b></p>    | <p><b>2</b></p>  <p><b>1 pc</b></p>    | <p><b>3</b></p>  <p><b>1 pc</b></p>    |
| <p><b>4</b></p>  <p><b>1 pc</b></p>    | <p><b>5</b></p>  <p><b>1 pc</b></p>    | <p><b>6</b></p>  <p><b>1 pc</b></p>    |
| <p><b>7</b></p>  <p><b>2 pcs</b></p>   | <p><b>8</b></p>  <p><b>4 pcs</b></p>   | <p><b>9</b></p>  <p><b>1 pc</b></p>    |
| <p><b>10</b></p>  <p><b>1 pc</b></p> | <p><b>11</b></p>  <p><b>1 pc</b></p> | <p><b>12</b></p>  <p><b>1 pc</b></p> |
| <p><b>13</b></p>  <p><b>1 pc</b></p> |                                                                                                                         |                                                                                                                           |

# HARDWARE LIST


|                                                                                                                           |                                                                                                                        |                                                                                                                           |
|---------------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------------------|
| <p><b>A X40+2</b></p>  <p>Ø6X30MM</p>    | <p><b>B X26+1</b></p>  <p>Ø6X40MM</p> | <p><b>C X26+1</b></p>  <p>Ø15X10MM</p> |
| <p><b>D X2</b></p>                       | <p><b>E X16+1</b></p>  <p>Ø4X50MM</p> | <p><b>F X2</b></p>                     |
| <p><b>G X2</b></p>                       | <p><b>H X10+1</b></p>                 | <p><b>I X2</b></p>  <p>96mm</p>        |
| <p><b>J X2</b></p>  <p>J1 J2 J3 J4</p> | <p><b>K X2</b></p>                  |                                      |




Bolt



Connecting piece




Adjust connecting piece direction until it is properly lined up with the hole.




Insert bolt when connecting piece direction is properly lined up.

1.




Pin  
Panel  
No gap


2.




3.





4.




## STEP 1




## STEP 2





# STEP 3




|          |                                                                                       |           |
|----------|---------------------------------------------------------------------------------------|-----------|
| <b>B</b> |    | <b>X6</b> |
| <b>D</b> |  | <b>X1</b> |


# STEP 4





|          |                                                                                       |           |
|----------|---------------------------------------------------------------------------------------|-----------|
| <b>A</b> |  | <b>X4</b> |
| <b>C</b> |  | <b>X4</b> |


# STEP 5




|   |                                                                                       |    |
|---|---------------------------------------------------------------------------------------|----|
| A |    | X6 |
| E |  | X6 |

# STEP 6





|   |                                                                                       |    |
|---|---------------------------------------------------------------------------------------|----|
| A |  | X6 |
| C |  | X6 |

STEP 7




STEP 8





|          |                                                                                       |            |
|----------|---------------------------------------------------------------------------------------|------------|
| <b>A</b> |  | <b>X10</b> |
| <b>E</b> |  | <b>X10</b> |

STEP 9




STEP 10




|     |             |     |
|-----|-------------|-----|
| (B) |             | X10 |
| (D) |             | X1  |
| (J) | J1 J2 J3 J4 | X2  |

# STEP 11




# STEP 12





**Please be sure to install the mending wedges to prevent the product from becoming unstable or wobbling.**

# STEP 13




Drill a hole in the wall , then hammer the J1 into the wall with a hammer



|   |    |    |    |    |    |
|---|----|----|----|----|----|
| J | J1 | J2 | J3 | J4 | X2 |
|---|----|----|----|----|----|


# STEP 14



|   |  |    |
|---|--|----|
| F |  | X2 |
| G |  | X2 |
| I |  | X2 |
| K |  | X2 |

# STEP 15

Please install accessory **F** firstly  
before installing accessory **G**.



# STEP 16

