


Assembly Instructions



① 1 PCS

② 1 PCS

③ 1 PCS

④ 1 PCS

⑤ 1 PCS

⑥ 1 PCS

⑦ 2 PCS

⑧ 1 PCS

⑨ 1 PCS

⑩ 1 PCS

A 20 PCS

M5X40

B 2 PCS

M4X19

M3


M4


STEP 1

pay attention to the orientation of the guide hole


NO.	QT
A	6PCS

STEP 2




NO.	QT
A	4PCS
	

STEP 3



NO.	QT	NO.	QT
A	2PCS	B	2PCS
			

STEP 4



STEP 5

