







An icon showing an L-shaped metal bracket inside a circle, and a power drill with a diagonal line through it, indicating that a power drill should not be used.	A warning triangle icon with an exclamation mark inside.	A clock icon showing a 30-minute duration.
An icon showing a rectangular block on a surface with a hatched area underneath, and a similar block with a hole and a diagonal line through it, indicating that a hole should not be drilled.	A warning triangle icon with an exclamation mark inside.	An icon of a person, representing one person.


30'

1




A	B	C
		
x 1	x 2	x 1

1




x 2

2




x 4

3




x 4

4




x 10

5





x 10

6













x 1

!










1

A  x 1	C  x 1	1  M6 x 45 x 2	3  M6 x 80 x 4	4  x 6	5  x 6	6  x 1
--	--	---	---	--	--	--







2

B  x 2	2  M6 x 60 x 4	4  x 4	5  x 4	6  x 1
--	---	--	--	--



3

6  x 1
--



!

