






Please don't tighten the screws completely and go back later for a final tightening of all the screws after pieces are aligned with each other.




A×1PC




B×2PCS




C×2PCS




D×4PCS



E×2PCS



F×2PCS



G×2PCS



H×2PCS



I×2PCS



J×2PCS



M6×10mm

K×16PCS




M6×25mm

L×4PCS



M6×40mm

M×20PCS




M6×50mm

N×8PCS




O×1PC

1




2




Tight all screws 100%

3




×2

4



×2

5



Tight all screws 100%

×2

