

Annual Maintenance for Outdoor Tables

Materials Needed:

- Clean, lint-free cloths
- Mild soap and water
- Protective gloves
- Drop cloth or newspapers

Steps:

1. Preparation:

- Clean the Table: Wipe down the table with a mixture of mild soap and water to remove any dirt, dust, or debris. Rinse with clean water and let it dry completely.

2. Application of Varathane Clear Satin Spar Urethane Spray:

- **Set Up:** Place the table on a drop cloth or newspapers in a well-ventilated area. Wear protective gloves to avoid contact with the spray.
- **Shake the Can:** Shake the Varathane Clear Satin Spar Urethane Spray can vigorously for about one minute to ensure it is well-mixed.
- **Test Spray:** Test the spray on a small, inconspicuous area to ensure compatibility and desired finish.
- **Apply the First Coat:** Hold the can 10-12 inches away from the surface and spray in a steady, back-and-forth motion, slightly overlapping each stroke. Apply a light, even coat.
- **Drying Time:** Allow the first coat to dry for at least 30 minutes. The finish should be dry to the touch.
- **Apply Additional Coats:** Repeat the spraying process for a total of at least 4 coats, allowing each coat to dry and sanding lightly between coats. This will provide maximum durability and UV protection.

3. Final Steps:

Cure Time: Allow the final coat to cure for at least 24 hours before using the table.

Regular Maintenance: Clean the table regularly with mild soap and water.