


Greenhouses for Outdoors


Product ID. 7A5RS







Scan for Support
support@garvee.com




Distributed by
GARVEE.com










1 x1




2 x11



3 x2



4 x2




5 x4




6 x4




7 x1




8 x1




9 x2



10 x2




11 x2



12 x2



13 x2



14 x2




15 x12



16 x12



17 x1



18 x1



19 x1



20 x1



21 x1



22 x1



23 x1




24 x1



25 x2




26 x2




27 x1



28 x2



29 x5




30 x2




31 x1



32 x3




33 x1




34 x2



35 x4




36 x2




37 x2




PARTS




HARDWARE






A x 3
M4x25




B x 4
M6x25






B x 4
M6x25




X2

B x 8
M6x25




X2

(B) x 4
M6x25




X2



(A) x 8
M4x25



X2




X2




X2



B x 6
M6x25







B x 6
M6x25





A x 8
M4x25







C x 4
M4x30




A x 4
M4x25




C



C x12
M4x30





C x10
M4x30




C x 4
M4x30





The hole spacing is wide on both sides






C x 6
M4x30




C x3
M4x30







A x 4
M4x25




E x 2




F x 8
M4x20



E x 2




F x 8
M4x20





A x 6
M4x25




B x 2
M6x25



C x12
M4x30



A x24
M4x25





C x4
M4x30




C

C




C x4
M4x30




44


C




C





D x 4
M4x50




C x 4
M4x30



D x 4
M4x50




C x 4
M4x30




F x 5
M4x20




G x 5









F x 5
M4x20




G x 5








I x 3
M4x60





J x 11
M3X10





K x 1




D x 2
M4x50





D x 2
M4x50




F x 8
M4x20





L x 2




F x 8
M4x20



L x 2




C x20
M4x30



D x2
M4x50



M x2
M4x40



D x 2
M4x50



M x 2
M4x40

