


INDUSTRIAL CEILING LAMP

ASSEMBLY INSTRUCTIONS


REMOVE ALL PARTS FROM PACKAGE, BE CAREFUL NOT
TO DAMAGE ANY COMPONENTS.




PROFESSIONAL INSTALLATION RECOMMENDED

INDUSTRIAL CEILING LAMP

REMOVE ALL PARTS FROM PACKAGE, BE CAREFUL NOT TO DAMAGE ANY COMPONENTS.



1. Detach mounting plate [C] from canopy [D].
2. Mounting plate [C] will attach to ceiling junction box.
3. Install the metal shade [A] onto socket [B] and tighten by using shade screws [F]. Install bulb 60W max (included with LED).
4. Install light to ceiling. We recommend installation by a qualified electrical professional. Canopy nuts [E] are used to tighten light to ceiling



Note: Turn off switch before replacing the bulb. Make sure the bulb has sufficient time to cool down.
Do not subject the lamp to any shock while lit as shattering of glass shade may result.