





















A1  x32	A2  x32	B5  10x50 x1	C1  8x35 x32	D1  x4
E6  x4	H33  x6	I  x1	N13  x6	P1  x16
Q  x12	R3  3x20 x38	R23  6,3x13 x8	R24  7x50 x16	R27  5,0x13 x40
R39  3,5x25 x6	R42  3x16 x12	R102  3,5x16 x8	S1  x14	S3  x6
S5  x28	S6  x1	Z15  250 x4		




№	a*b*c	x	№→...
1	1000x350x16	1	1/2
2	1000x350x16	1	1/2
3	788x348x16	2	1/2
5	788x312x16	1	1/2
6	788x312x16	1	1/2
7	290x300x16	4	2/2
8	364x178x16	3	1/2
9	364x234x16	1	1/2
10	300x100x16	3	2/2
11	300x100x16	3	2/2
12	300x200x16	1	2/2
13	300x200x16	1	2/2
14	292x100x16	3	2/2
15	292x200x16	1	2/2
16	780x296x16	2	2/2
17	800x306x2,5	2	2/2
18	800x366x2,5	1	1/2
19	322x305x2,5	4	2/2
			






1






A2  x8	C1  8x35 x8	P1  x8	R27  5,0x13 x24	Z15  250 x4
--	--	--	--	--



2




3




4x2

A2  x8	C1  8x35 x8	D1  x4	P1  x8	R23  6,3x13 x8
--	--	--	--	--







5


S5  x2
--







6










7



8





9



10_{x3}

A2  x12	C1  8x35 x12	H33  x3	I  x1
--	---	--	--


R3  3x20 x24	R24  7x50 x12	R27  5,0x13 x12	R42  3x16 x6	S5  x12	Z15  250 x3
--	---	---	--	---	--



11


A2  x4	C1  8x35 x4	H33  x1	I  x1
---	---	--	--

R3  3x20 x8	R24  7x50 x4	R27  5,0x13 x4	R42  3x16 x2	S5  x4	Z15  250 x1
--	---	---	---	--	---



12

E6  x4	R102  3,5x16 x8	H33  x2	R42  3x16 x4
--	---	---	--



13

