






Product Usage Instructions



NO JUMPING





INSTALLATION GUIDE













Suggest using electric tools for installation


SKU:16031S








A		65 PCS	J	 J-1 J-2	2 PCS
B	 M15	65 PCS	T	 T00L	1 PCS
C	 80*80	6 PCS	K		12 PCS
E	 M4*30	25 PCS	L		8 PCS
D	 M8*40	13 PCS	O	 O-1 O-2	2 PCS
F	 M3.5*14	130 PCS	P		1 PCS
H	 M4*18	4 PCS	Q		6 PCS
I		4 PCS	R	 M6*13	25 PCS
S	 M6*18	8 PCS	X	 M15*150	4 PCS
Z		2 PCS	M	 M50	1 PCS

Special hardware install instructions





Special hardware removal instructions




A		8 PCS	B	 M15	8 PCS
M	 M50	1 PCS			



STEP 1




A		8 PCS	B	 M15	8 PCS
---	---	-------	---	--	-------



STEP 2




A		8 PCS	D		4 PCS
B	 M15	8 PCS			


STEP 3




P		1 PCS	F	 M3.5*14	2 PCS
C	 80*80	2 PCS	R	 M6*13	8 PCS
A		10 PCS	D		4 PCS



STEP 4




A		4 PCS	B	 M15	14 PCS
---	--	-------	---	---	--------


STEP 5





F	 M3.5*14	10PCS	O	 O-1	2 PCS
---	--	-------	---	--	-------


Q		6 PCS
---	---	-------


STEP 6




A		10 PCS	B	 M15	10 PCS
F	 M3.5*14	8 PCS	O	 O-2	2 PCS
D		4 PCS	J	 J-2	2 PCS


STEP 7




A		2 PCS	B	 M15	2 PCS
F	 M3.5*14	6 PCS	K		3 PCS



STEP 8




A		6 PCS	B	 M15	6 PCS
---	--	-------	---	---	-------


STEP 9




A		2 PCS	B	 M15	2 PCS
F	 M3.5*14	6 PCS	K		3 PCS


STEP 10




A		6 PCS	B	 M15	6 PCS
---	--	-------	---	---	-------

STEP 11




E	 M4*30	8 PCS	K		6 PCS
F	 M3.5*14	12 PCS			

STEP 12




E




M4*30

8 PCS

STEP 13




E




M4*30


8 PCS


STEP 14




H	 M4*20	2 PCS	I	 	2 PCS
S	 M6*18	8 PCS			

STEP 15



H	 M4*20	2 PCS	I	 	2 PCS
C	 80*80	2 PCS	R	 M6*13	8 PCS

STEP 16



C



80*80

2 PCS


R





M6*13

8 PCS




STEP 17





STEP 18





STEP 19



F	 M3.5*14	80 PCS	L		8 PCS
X	 M15*150	4 PCS			

STEP 20



F	 M3.5*14	4 PCS	J	 J-1	2 PCS
Z		2 PCS			

STEP 21

