











LIFE CARVER








WF189221AAA














Parts for frame listing


<p>①</p>  <p>x1</p>	<p>②</p>  <p>x1</p>	<p>③</p>  <p>x1</p>	<p>④</p>  <p>x1</p>
<p>⑤</p>  <p>x1</p>	<p>⑥</p>  <p>x1</p>	<p>⑦</p>  <p>x1</p>	<p>⑧</p>  <p>x1</p>

Parts for drawers listing


<p>⑨</p>  <p>x3</p>	<p>⑩</p>  <p>x3</p>	<p>⑪</p>  <p>x3</p>	<p>⑫</p>  <p>x3</p>	<p>⑬</p>  <p>x3</p>
--	--	--	--	--

Hardware listing



<p>A</p> <p>Ø8x30mm</p>  <p>x8</p>	<p>B</p> <p>Ø6x35mm</p>  <p>x24</p>	<p>C</p> <p>Ø15x9mm</p>  <p>x24</p>	<p>D</p> <p>Ø3x13mm</p>  <p>x12</p>
<p>E</p>  <p>x3</p>	<p>F</p> <p>M4x22mm</p>  <p>x3</p>	<p>G</p> <p>12"</p>  <p>x3</p>	
<p>H</p> <p>Ø3x12mm</p>  <p>x24</p>	<p>I</p> <p>Ø4x35mm</p>  <p>x4</p>	<p>J</p> <p>Ø3x25mm</p>  <p>x12</p>	<p>M</p>  <p>x1</p>




5X45mm bolt installation as below




STEP




STEP




STEP




1



SCREWS	
A	Ø8x30mm x4
B	Ø6x35mm x4




2




SCREWS	
A	Ø8x30mm x4
B	Ø6x35mm x8
G1	x6
H	Ø3x12mm x12

3




4

SCREWS
C Ø15x9mm
x4




5


SCREWS
C Ø15x9mm
x4



6



7




SCREWS

C \varnothing 15x9mm
x4

I \varnothing 4x35mm
x4

8




SCREWS

D \varnothing 3x13mm
x12

9


SCREWS
 B \varnothing 6x35mm x12



x3

10


SCREWS
 J \varnothing 3x25mm x12



x3

11


SCREWS
 E \varnothing x3
 F M4x22mm x3
 C \varnothing 15x9mm x12



x3



12


SCREWS
 G2 x8
 H \varnothing 3x12mm x16



x3

13

SCREWS	
G2	 x6
H	 Ø3x12mm x12



14

