





ASSEMBLY INSTRUCTION




PARTS LIST


					
A	B	C	D	E	F
X1	X1	X1	X1	X1	X1
					
G					
X1					

HARDWARE LIST


					
1					
X6					




Step1




Step2




Step3




Step4





Step5




Step6





Step7



ASSEMBLY INSTRUCTION





PARTS LIST

				
A	B	C	D	
X1	X1	X1	X1	


HARDWARE LIST

	
1	X4


Step1




Step2





Step3




Step4






Step5




ASSEMBLY INSTRUCTION




PARTS LIST

					
A	B	C	D	E	F
X1	X1	X1	X1	X1	X1


	
G	
X1	

HARDWARE LIST


	
1	
X6	




Step1




Step2




Step3




Step4





Step5




Step6



Step7



ASSEMBLY INSTRUCTION





PARTS LIST


			
A	X1	B	X1

HARDWARE LIST


	
1	X4







Step2




ASSEMBLY INSTRUCTION




PARTS LIST


					
A	B	C	D	E	F
X1	X1	X1	X1	X1	X1

HARDWARE LIST


 Ø 55X30mm	
1	G
X4	X2




Step1




Step2




Step3



Step4



Step5



Step6

