





Assembly Instructions




29



- | | | | | | |
|----------|---|--------|----------|---|--------|
| E |  | [×8] | Q |  | [×2] |
| F |  | [×8] | | | |




×139



(A)

34mm

×123



(B)

Ø15*12mm


×76



(C)

Ø8*30mm

×16



(D)

Ø15*10mm


×8



(E)


Ø3*18mm

×8



(F)


×6



(G)

孔距128mm

×4



(H)


M4*22mm

×7



(J)


×14



(K)

Ø4*15mm


×16



(L)

Ø5*38mm


×2




(M)

30*17*17mm


28



27




R



[×16]

×4


(N)



350*27mm

×4


(P)



113*42mm


×2

(Q)



×42


(R)



Ø3.5*12mm

×4


(T)



13*Ø8*25mm

×8


(S)



M4*16mm

×2


(V)



L42*W16*1.5mm

×2


(W)



4mm*24*70

×48


(U)





Ø3.5*11mm

1

Please fasten the screws through these holes for this step



Please fasten the screws through these holes for this step



(A) [×26]




(N) [×4]

(M) [×1]

(R) [×2]

(U) Ø3.5*11mm [×12]

26




(G) [×2]

(H) [×4]


(P) [×4]

(R) [×16]


25



× 4




× 4




- | | | | | | |
|-----|--|---------|-----|--|---------|
| (A) | | [×16] | (D) | | [×16] |
| (G) | | [×4] | (S) | | [×8] |



2



× 2





× 2



× 2

- | | | | | | |
|-----|--|---------|-----|--|---------|
| (A) | | [×12] | (C) | | [×24] |
| (J) | | [×4] | (K) | | [×8] |

3




B




[×12]

24




N




[×8]

L




[×16]


U





[×24]


23




- T  [×4]
 W  [×2]

4



- A  [×4]
 B  [×4]
- C  [×16]

5




B



[×10]

22




C



[×9]

21




C




[×9]

6



7




B



[×10]

20




C



[×3]

19






C



[×6]

8




B



[×6]


R



[×1]





9

Please fasten the screws through these holes for this step






Please fasten the screws through these holes for this step




- | | | | | | |
|-----|---|---------|-----|---|--------|
| (A) |  | [×26] | (N) |  | [×4] |
| (M) |  | [×1] | (R) |  | [×2] |
| (U) |  | [×12] | | | |
- Ø3.5*11mm


18




- | | | | | | |
|-----|---|--------|-----|---|--------|
| (A) |  | [×6] | (C) |  | [×6] |
| (C) |  | [×3] | | | |

17




A  [×24] **C**  [×16]

10





B  [×10]

11



16




B




[×12]

V





[×2]

S



[×4]

15





B



[×13]

12







B





[×10]


13



B  [×6] **R**  [×1]

14



A  [×25] **C**  [×14]
J  [×3] **K**  [×6]