

# CABINET USE & CARE

---



WOOD

---

Spray with mild, soapy solution or water and vinegar mixture. Wipe immediately with a clean rag to remove the soap residue. Do not let water sit on the hardware.

---



CERAMIC

---

Rub with a damp rag or cloth.

---



GLASS

---

Spray with glass cleaner or water and vinegar solution. Wipe clean with rag or cloth.

---



METAL

---

Spray with mild, soapy solution or water and vinegar mixture. Wipe with a clean rag to remove the soap residue. Alternate method: Remove hardware using a screw driver. Soak in a soapy solution for several hours or overnight. Rinse and thoroughly dry prior to installation.

---