






Installation & Assembly



EN_IMPORTANT, RETAIN FOR FUTURE REFERENCE: READ CAREFULLY.

. THANK YOU FOR PURCHASE! .

FREE REPLACEMENT PARTS AVAILABLE!



---NEED HELP WITH YOUR FURNITURE?---










If you're experiencing any issues—whether due to shipping, assembly, or any other reason
—we're here to help.



For any damaged or missing components, we're happy to provide FREE replacement parts.


WANT TO CONTACT US ?

- ▶ Log in to your account.
- ▶ Go to “Your Orders” and locate your furniture order.
- ▶ Click on “Get Help with Order” to send us a message directly.


Our customer support team is ready to assist you and we will respond within
12-24 HOURS to resolve your concerns quickly!



NO.	PARTS	QTY	SPARE
①		x1	
②		x1	
③		x1	
④		x4	
⑤		x6	
⑥		x3	
⑦		x3	
⑧		x1	
	 Hardware Kit	x1	









01












M x14



When the diagonals are equal, please first install the screws at the marked positions to fix the backboard, and then proceed to install the remaining screws. Otherwise, installation may cause the backboard to tilt.



B x2
Ø3.5x12mm




M-2



M-3



K x1




B x18
Ø3.5x12mm

L x3

R x3


⑦ x3



x3

B x6
Ø3.5x12mm




⑥ x3





x3

B x4
Ø3.5x12mm


5 x2



OR



OR



A x2
Ø4x40mm

I x2
Ø6x30mm



WALL

I x2


WALL +


drilling hole
Ø6x30mm

II x2



WALL

III x2






When installing E-3, it is sufficient to reach 90% progress. Installing 100% may cause damage to E-2.





B x2
Ø3.5x12mm



5 x1




WALL



OR



OR



K x1

K-1



WALL

Power
supply

K-1

