## Assembly Instruction

Parts/Hardware list					
A Top Shelf	1PC	E	Bottom Shelf (Empty)	1 PC	
B Connectors	4 PCS	F	Ribbed Tube (Long)	4 PCS	
C Threaded Rod	4 PCS	G	Stretcher	1 PCS	
D Ribbed Tube(Short)	4 PCS	H	Feet	4 PCS	
Mirror(for Top shelf)	1PC		Tempered Glass (for bottom)	<u> 1 PC</u>	
Felt(for top mirror)	6PCS		Screws	4 PCS	
fear F	В — В	1	Finial	I PC	
	A	1. Т flat	Take the parts carefully out of and soft surface, making sur	The carton, and place them on a e that the parts will not be damaged.	
<u>a</u>	ė.			e down on a flat & soft surface,	
с с			and then lift it a little bit at one corner and insert 1 screw from the scre		
			hole at the side of the bottom, then tighten one Connector (B) at the		
			other side until secure. Repeat this step to secure all the other three Connectors (B) with the Top Shelf (A).		
	A	Col	nnectors (B) with the Top Sil	en (A).	
/ 63 Ad				ed Rods (C) into the 4 Connectors(B).	
		ma anc	king sure that the bottom of t	rt, D) go through the Threaded Rods ( he tubes align with the Connectors (B) the Bottom Shelf (E, empty) go throug	
p	1.1. manual of the second of t	Sho (Lo	elf (E), and then put the Stret	Ribbed Tube (Long, F) onto the Botton cher (G) onto the top of Ribbed Tube crew the four feet (H) to secure all the	
			Screw the finial (1) on the co		
		Во		fully place the Tempered Glass onto the Mirror onto the Top Shelf (A). If the felt(included).	
		То	Clean, wipe with soft dry cl	oth.	