


Assembly Instructions



Side Table






Contact Us

We're here to help you.

Your satisfaction is our top priority. If you encounter any issues with this product, such as missing or damaged parts, we're here to help. Please retain the original packaging and take photos of the packaging and the product, then contact us as soon as possible.


Warm Tips


1. Carefully read these instructions and keep them for future reference.
2. Check the parts list and confirm everything's there before starting assembly.
3. When assembling, put all parts on a soft, smooth surface like a carpet to avoid scratches.
4. Don't fully tighten screws until all parts are confirmed in place to avoid misalignment.



We recommend using hand tools for assembly.

If an electric screwdriver is used, reduce power and torque to avoid damage to the product.





⚠ Caution


Make sure all parts are included. Most board parts are labeled or stamped on the raw edge. Contact us for a free replacement if you encounter any damaged or missing parts.




Parts List



① 1pc



② 2 pcs




③ 1pc



④ 2 pcs



⑤ 1pc



⑥ 2 pcs



Hardware List

A	X15+1	B	X2+1	C	X4+1	D	X1	E	X4
M6X30 mm		M6X40 mm		Ø7X37 mm		M4X55 mm		M6XØ20 mm	



1


pre-drill 70%



A	X4	D	X1
M6X30 mm		M4X55 mm	

2


pre-drill 70%



A	X2
M6X30 mm	




3



A	X4	C	X4	E	X4
M6X30 mm		Ø7X37 mm		M6XØ20 mm	


4






A	X2	B	X2
M6X30 mm		M6X40 mm	




5



screw down 


A	X3
	
M6X30 mm	

6



Thank you for your support!

