




SKU: P0000501






# Parts List




1

1PC




2

1PC




3

1PC




4

1PC




5

2PC




6

1PC




7

1PC




8

1PC




9

1PC




10

1PC




11

1PC



12


2PC




13

3PC


# Hardware List




A 19PC




$\phi 15$   
B 19PC




$\text{Ø}8*30\text{mm}$   
C 16PC




$\text{Ø}4*40\text{mm}$   
D 13PC




E 4PC




$\phi 3*14\text{mm}$   
F 24PC




G 4PC



$\text{Ø}4*30\text{mm}$   
H 6PC






M6\*25mm  
I 4PC







$\phi 3*12\text{mm}$   
J 24PC




# STEP 1






# STEP 2




# STEP 3






# STEP 4





# STEP 5




# STEP 6







# STEP 7



# STEP 8



# STEP 9




# STEP 10









M6\*25mm

I




4PC



# STEP 11



# STEP 12



# STEP 13

---

