




Assembly Instructions




HARDWARE LIST




A x 1pc




B x 1pc




C x 1pc




D x 1pc




E x 1pc




F x 1pc




G x 1pc




H x 3pcs



J x 1pc



K x 2pcs





L x 1pc

PARTA LIST



M5 x 40mm

① x 37pcs



M3 X 16MM

② x 8pcs




M3

③ x 1pc



M5



④ x 1pc




M3 x 14mm
M4 x 40mm

⑤ x 1pc


STEP 1




- A x 1pc
- B x 1pc
- H x 2pcs
- ① x 8pcs



STEP 2




- A x 1pc
- B x 1pc
- H x 2pcs
- ① x 4pcs



STEP 3


K x 2pcs



STEP 4

D x 1pc


① x 6pcs



STEP 5


E x 1pc

① x 6pcs



STEP 6


J x 1pc



STEP 7

C x 1pc


① x 4pcs



STEP 8

G x 1pc


① x 5pcs



STEP 9


F x 1pc

① x 4pcs



STEP 10

② x 12pcs



② x 8pcs

STEP 11

5 x 1pc

