







Diagram illustrating assembly instructions and safety warnings:

- Top Section:** A box containing a crossed-out power drill icon and a warning triangle with an exclamation mark. To the right is a clock icon with the text **10'** below it.
- Bottom Section:** A box containing two icons: a block being placed on a textured surface (circled) and a crossed-out block with a screw being inserted. To the right is a person icon with the text **1** below it.


A




C







B x 3






D x 3



A	B	C	D
			
x 1	x 3	x 1	x 3

1



2

