



Assembly Manual



1




1pc

2



1pc

3



1pc

4




8pcs

5



1pc

6



1pc

7








2pcs

8




1pc

9  3pcs	10  1pc
11  2pcs	12  2pcs
13  1pc	14  1pc
15  1pc	16  1pc
17  1pc	


Before assembly, please put all parts on a neat and clean sheet

Assembly Manual

Hardware Accessories								
NO.	PICTURE	SIZE	QTY		NO.	PICTURE	SIZE	QTY
A			5		B		M6 * L25mm	14
C		M6 * L30mm	10		D		M6 * L35mm	29
E		M6 * L50 mm	1		F		M4 * L25 mm	6
G		M6 * T5	4		H			1
I			1		J			1




SPARE								
NO.	PICTURE	SIZE	QTY		NO.	PICTURE	SIZE	QTY
B		M6*L25mm	1		C		M6*L30mm	1
D		M6*L35mm	1		E		M6*L50mm	1
F		M4*L25mm	1		G			1

Exploded View.




Installation procedures

step 1




A=5X

step 2




D = 28X




Due to many accessories, please carefully check the instructions for installation


step 3




B = 4X




step 4



F = 6X



step 5





C = 4X


B = 4X

G = 4X







step 8




B = 2X



step 9



C = 4X



COMPLETED DRAWING

