


- 1: Longest screw
- 2: Long screw
- 3: Short screw
- 4: Shortest screw



- Metal plate*1
- Portable screwdriver*1
- Pneumatic kit*1




Step 1: Put the switch, handle and flip on the column and fix it with screw number 2



Step 2: Place the connecting piece on top of the flip piece and fix it with screw number 4



Step 3: Place the connecting piece on the base bracket and fix it with Screw number 3



Step 4: Put the base on the column and fix it with screw number 1