


D38"H53"L12+6+3



We are dedicated to providing the finest quality crystal chandelier for our customers. Our master craftsmen and designer pride themselves on their attention to detail.

prompt,efficient service is our priority.

Enclosed,are detailed instructions on how to properly install your chandelier.Please read all instructions carefully and thoroughly.If you have any questions please fell free to call our toll free CHANDELIER HOTLINE



D38"H53"L12+6+3

WARNING!!!

CONTENTS ARE FRAGILE
HANDLE WITH CARE

The metal frame and crystal components of this chandelier are very delicate. Please exercise extreme caution during unpacking and installation.

WARNING!!!

After passing the main electrical wire through the 10mm pipe and connecting the pipe to the main body top connector, place all remaining pieces as shown in numerical order and in the orientation depicted. Refer to the parts list to avoid confusion between parts. The part numbers coincide.


CAUTION

1. Rated 110-130V/60Hz, bulb 40W maximum
2. Care should be taken to avoid damage to the surface of lighting and wire, wearing gloves is recommended when installing.
3. Connect black or red wire of the lighting to live wire and white or blue wire to neutral wire and double colored (or bare copper) wire to ground wire.
4. Never install lighting on damp ceiling, the room should be dry and well ventilated.
5. Keep lighting away from acid, alkali and other corrosive chemical or gas, clean the lighting with clean soft cloth only.
6. Installation must be carried out by qualified electrician only.
7. Disconnect the power before installing, cleaning and replacing lighting.
8. Never cover the lighting when power is connected.
9. Firmness must be secured when installing ceiling tube, chain, pipe and other connecting parts.
10. Care should be taken to avoid damage when installing glass parts.
11. All electrical components must be installed by a licensed electrician and in accordance with the National Electrical Code and the appropriate local electrical codes. Make sure that the electrical supply to the chandelier is turned off at the main fuse or circuit breaker before doing any installation.

D38"H53"L12+6+3

Crystal Dressing Instructions

When dressing the chandelier with the crystals please remember to wear either rubber or cotton gloves. So as to prevent any damage or smudging on the crystals.




| No | Quantity |
|----|------------|
| A | 4 strings |
| B | 12 strings |
| C | 3 strings |
| D | 3 strings |
| E | 24 strings |
| F | 6 strings |
| G | 6 strings |
| H | 48 strings |
| I | 12 strings |
| J | 12 strings |
| K | 12 strings |
| L | 4 strings |
| M | 1 strings |
| N | 12 strings |
| O | 12 strings |
| P | 12 strings |
| Q | 6 strings |
| R | 3 strings |

D38"H53"L12+6+3

Crystal Dressing Diagram



When dressing the chandelier with the crystals please remember to wear either rubber or cotton gloves. So as to prevent any damage or smudging on the crystals.



Connect both ends of O with I


Connect both ends of N with J

09

D38"H53"L12+6+3

CANOPY PARTS LIST


ZA: Existing Electrical Box (not supplied)



ZB: Crossbar




ZC: Crossbar Screws x 2 (not supplied)



ZD: Canopy lock



ZE: Canopy



ZF: Metal Ring




ZG: Chain



ZH: Ground Wire




ZI: Canopy Loop



ZJ: Electric Main




ZK: Junction Caps



02

D38"H53"L12+6+3

CANOPY INSTALLATION DIAGRAM



03

D38"H53"L12+6+3

Frame Assembly Instruction

Please read all instructions carefully. Before you proceed to install, make sure that the power supply is tamed off and off until installation is complete. Please note that each part has been assigned a letter. Please proceed in alphabetical order.

1. Install (Cast Canopy)01 to the electric Box and wire properly.
2. Fixed (Chain Connector)02 with (All Thread)09 and fasten (Ground Screw)35.
3. Wear (Crystal Ring)20 on (Glass Arm)21.
4. Fixed (Glass Arm)21 with (Round Metal Slice)12 by (Spring Seat)19, (Set Screw)17
5. Connected cable of (Glass Arm)21 with main cable.
6. Fixed (Bottom Cover)15, (Crystal Bowl)14, (Straight edge cover)06, (Glass Column)07, (Straight edge cover)08, (Direct Connection)10 and (Round Metal Slice)36, on from (Metal tube)16
7. Wear (Crystal Ring)20 on (Glass Arm)26.
8. Fixed (Glass Arm)26 with (Round Metal Slice)36 by (Spring Seat)19, (Set Screw)17
9. Fixed (Bottom Cover)15, (Crystal Bowl)14, (Straight edge cover)06, (Glass Column)07, (Straight edge cover)08, (Direct Connection)10 and (Round Metal Slice)33, on from (Metal tube)16
10. Wear (Crystal Ring)20 on (Glass Arm)34.
11. Fixed (Glass Arm)34 with (Round Metal Slice)33 by (Spring Seat)19, (Set Screw)17
12. Take out the (Sleeve Cover)25, and put (Crystal Bowl)05 and then put back (Sleeve Cover)25
13. Take (Cast Bottom Finial)27, (Bottom Cover)31, (Crystal Bowl)30, (Iron piece)29, (Crystal Bowl)05 and (Ring)28 off from (All Thread)32. by (Cast Bottom Finial)27
14. Fixed (Cast Bottom Finial)27, (Bottom Cover)31, (Crystal Bowl)30, (Iron piece)29, (Crystal Bowl)05 and (Ring)28 on from (All Thread)32
15. Dressing Crystal using Diagram provided.

The end!

08

D38"H53"L12+6+3


Fram Parts List



21-Glass Arm



28-Ring



34-Glass Arm



22-Sleeve cover



29-Iron piece




35-Ground Screw



23-All thread




30-Crystal Bowl



36-Round Metal Slice



24-Socket



31-Bottom Cover



25-Sleeve cover




26-Glass Arm



32-All thread



27-Cast Bottom Finial



33-Round Metal Slice

D38"H53"L12+6+3

CANOPY INSTALLATION INSTRUCTIONS

Please read all instructions carefully. Before you proceed to install, make sure that the power supply is tamed off and off until installation is complete. Please note that each part has been assigned a letter. Please proceed in alphabetical order.

ZA. Junction Box (not supplied)

ZB. Crossbar

ZC. Crossbar Screws

ZD. Canopy Loop

ZE. Canopy

ZF. Metal Ring

ZG. Chain

ZH. Ground Wire

ZI. Canopy loop


ZJ. Electric loop

ZK. Junction Caps

1. Attach the Crossbar (ZB) to the Junction Box (ZA) using the two crossbar screws (ZC) which are not supplied and should already be in your box.
2. Slide the Metal Ring (ZF) back up over the canopy (ZE), pass the canopy loop (ZD) through canopy (ZE), connect with the threaded pipe underside of the crossbar.
3. Pass the electric loop (ZJ) and ground wire (ZH) through the chain (ZG), the Metal Ring (ZF), the canopy (ZE), the canopy loop (ZD) and the crossbar (ZB) until the end of the electric Loop (ZJ) reaches the junction box (ZA) where you can make the appropriate connections.
4. Be sure when connecting the wire use electrician approved junction caps (ZK).
5. Stow the excess wire in the junction box (ZA).
6. Raise the canopy (ZE).
7. Metal Ring (ZF), attach canopy (ZE) to ceiling, slide Metal Ring (ZF) over canopy loop (ZD) and hold the canopy (ZE).

D38"H53"L12+6+3





















Frame Assembly Diagram



05

D38"H53"L12+6+3

Fram Parts List

- | | | |
|---|---|---|
|  |  |  |
| 01-Cast Canopy | 07-Glass Column | 14-Crystal Bowl |
|  |  |  |
| 02-chain Connector | 08-Straight edge cover | 15-Bottom Cover |
|  |  |  |
| 03-Set Screw | 09-Metal tube | 16-Metal tube |
|  |  |  |
| 04-Plastic Spacers | 10-Direct Connection | 17-Set Screw |
|  |  |  |
| 05-Crystal Bowl | 11-All thread | 18-All thread |
|  |  |  |
| 06-Straight edge cover | 12-Round Metal Slice | 19-Spring Seat |
|  |  | |
| 13-Nut | 20-Glass Ring | |

06