





Code	A	B
Iron		
Number	4PS	8PS


WDC2430,
WDC2436
WDC2442




Example




Step 1




Step 3



Step 2



Step 4



Step 5

