






"IMPORTANT, RETAIN FOR FUTURE REFERENCE: READ CAREFULLY"



1. Periodically check that all components are tightly secured.
2. Assemble on a flat, clean, and soft surface.
3. Confirm all parts are present prior to assembly.



R 4*50  2PCS	S 3.5*14  2PCS	T  18PCS
K  2PCS	L 6*12  4PCS	M 6*30  4PCS
A  39PCS	B  39PCS	C 8*40  17PCS


N  1PCS
D 7*50  12PCS

E  12PCS
--

F 3.5*14  4PCS
--

G 3*12  34PCS


H  34PCS

I  1PCS
--

J J ₁ J ₂   2PCS


U  6PCS	 1PCS
P  2PCS	Q 8*40  2PCS
O  4PCS	

1




A*22 C*6

2




A*17 C*11

3




B*4


4




5




6




7



8




9




B*1 D*2

10




B*4

11




12




B*6

13




B*6

14




15




D*6

16




B*10 T*18 U*6

17




E*12

18







19







F*2 M*4 N*1 0*4

20












G*34 H*34 J*2

23



I*1 F*2

24



P*2 Q*2 R*2 S*2