

Instructions


⚠ WARNING

- Check for electric, gas, & plumbing lines before drilling or consult a professional.
- Turn off your electricity at the circuit breaker or main fuse box before installation. Do not restore power to the line until the light has been fully installed.
- Do not use with bulbs exceeding the recommended wattage.
- Always switch off the electricity supply and allow bulbs to cool for 10 minutes before changing it.
- Do not look directly at lit bulb.

ASSEMBLY

It is recommended to use two or more persons during the assembly process.

1. Install the Lamp Holder Bracket (H) onto the Junction Box (J) and secure it with a hex nut
2. Connect the power cord with the terminal block and pay attention to distinguishing the positive and negative poles
3. Connect Stele (G) to Junction box (J) and thread the power cord through Stele (G)
4. Connect Sling chain (F) to Stele (G) and choose the length you need
5. Cover the Horn hood (I) on top of the Junction box (J) and secure it with a Fixed sphere (K)
6. Secure the Mounting Bracket (C) to the Junction BOX (A) with matching screws
7. Cover the Wiring terminals (B) with Canopy (D) and tighten them using Canopy Nut (E)
8. Twist in E12 bulb (not included)
9. After installation is completed, turn on the power switch and test whether the lighting fixtures are on. Due to the large size of the lamp body and the relatively complex installation, it is recommended to have a professional electrician complete it!



Just Scan the Below Code for Installation Video



311B

d1		x 3
d2		x 2

E12 Socket Max
.60W Bulbs
(not included)