

















Assembly Instruction








1  599x298x15 x1	2  545x206 x2	3  537mm x1	4  537x249x12 x3
5  538x284x15 x1	6  884x285x15 x1	7  472x272 x2	8  464mm x1
9  884x285x15 x1	10  569x285x15 x1	11  785x285x15 x1	12  697x271 x2
13  689mm x1	14  785x285x15 x1	15  538x249x12 x1	16  538x284x15 x1
17  538x79x15 x1	18  458x265x15 x2	19  683x265x16 x1	20  683x265x16 x1

A x 25+3  Φ6X35mm	B x 25+3  Φ15X10mm	C x 18+2  Φ6X30mm	D x 4  Φ5X40mm	E x 36+3  Φ3X12mm
F x 4  Φ3X14mm	G x 4 	H x 4 H-1 H-2  Φ4X30mm	I x 8 	J x 4 
K x 2 	L x 2 L-1 L-2  Φ4X12mm	M x 4  Φ21	N x 12  5mm	O x 24+1 O-1 O-2  Φ3X16mm
P x 2 P-1 P-2 P-3  Φ4X45mm				



1







When turning the screw, please be slowly. First, use your hand to align the screw, position it in the screw hole, and then tighten it.



180°


A  x 5	L L-1 L-2  x 2
--	---


2




E  x 20	H H-1 H-2  x 4	I  x 8	J  x 4
--	--	---	---


3





A	F	K	N
			
x 4	x 2	x 1	x 8

4



A	F	K	N
			
x 16	x 2	x 1	x 4

5




B




x 4

6



7



C





x 4

D




x 4

8





9




C  x 4	B  x 4
	M  x 4


10




B  x 1	C  x 2
---	---

11





B	C	G
		
x 12	x 4	x 4

12




13





B	C
	
x 4	x 4



14






15



16



17



18

