


Assembly Instruction

①




X2

②



X1

③



X10

M6×20


④



X10

M6 spacer

⑤



X1


Wrench

⑥




X10

Plastic cap



①



②