
















ASSEMBLING INSTRUCTION

A x2PC 	B x1PC 	C x2PC 	D x2PC 	E x6PC 
F x4PC M6 x 20 	G x2PC M6 x 60 	H x12PC 	I x1PC 5# 	J x12PC 
K x12PC 	L x1PC 	M x1PC 	N x6PC 	



After rechecking all parts and screws to make sure they are in the correct position, tighten the screws to 100%

Vuelva a comprobar todos los tornillos y piezas para asegurarse de que están en las posiciones correctas y apriete todos los tornillos al 100%