


# ASSEMBLY INSTRUCTION


Description : Bar Set

Thank you for purchasing this quality product. Be sure to check all packing material carefully for small parts that may have come loose inside the carton during shipment.


Step 1:



Step 2:



Step 3:



## PART LIST:

No.	Description	Diagram	Quantity
A	Chair Back		1
B	Seat Cushion		1
C	Chair Left Leg		1
D	Chair Right Leg		1
E	Left Stretcher		1
F	Right Stretcher		1
G	Front Stretcher		1
H	Table Top		1
I	Table Legs		4

## HARDWARE LIST:

No.	Description	Diagram	size	Quantity
J	Bolt		Ø5/16" x 3-1/4"	16
K	Bolt		Ø5/16" x 2-1/4"	24
L	Bolt		Ø5/16" x 1-3/4"	8
M	Screw		35mm	24
N	Lock Washer		Ø5/16"	48
O	Flat Washer		Ø5/16"	48
P	Allen Key		M5	5


# ASSEMBLY INSTRUCTION

Description : Bar Set


Thank you for purchasing this quality product. Be sure to check all packing material carefully for small parts that may have come loose inside the carton during shipment.

Step 1:










" Move out the corner wood block and discard the wood block and bolts"










Step 2:



PART LIST:

No.	Description	Diagram	Quantity
A	Chair Back		1
B	Seat Cushion		1
C	Chair Left Leg		1
D	Chair Right Leg		1
E	Left Stretcher		1
F	Right Stretcher		1
G	Front Stretcher		1
H	Table Top		1
I	Table Legs		4

HARDWARE LIST:

No.	Description	Diagram	size	Quantity
J	Bolt		Ø5/16" x 3-1/4"	16
K	Bolt		Ø5/16" x 2-1/4"	24
L	Bolt		Ø5/16" x 1-3/4"	8
M	Screw		35MM	24
N	Lock Washer		Ø5/16"	48
O	Flat Washer		Ø5/16"	48
P	Allen Key		M5	5

Finished

