



















ASSEMBLY INSTRUCTIONS







Hardware


A x 8  Ø 6 x 35 mm (LONG)	B x 2  Ø 6 x 32 mm (SHORT)	C x 8  Ø 15 mm (Big)	D x 2  Ø 12 mm (Small)
E x 16  Ø 8 x 30 mm (Big)	F x 2  Ø 6 x 30 mm (Small)	G x 1 	H x 4 
I x 4 	J x 6 	K x 2 	L x 8 
M x 4 	N x 4 	O x 4 	RM35A x 1 


 SET-UP TIME : 90 MINUTES	 NUMBER OF PERSONS : 02	 TOOLS : (Not Provided)
--	---	---


1


B x 2  Ø 6 x 32 mm (SHORT)	F x 2  Ø 6 x 30 mm (Small)
--	--

2





D	x 2
	
Ø 12 mm (Small)	





I	x 4
	


3




J	x 6
	


RM35A	x 1
	




K	x 2
	


4





E	x 12
	
Ø 8 x 30 mm (Big)	


A	x 8
	
Ø 6 x 35 mm (LONG)	




5





H	x 4
	

RM35A	x 1
	



6

L	x 8	G	x 1	E	x 4
				 Ø 8 x 30 mm (Big)	



7

C	x 2
	
Ø 15 mm (Big)	



8



9





10





N	x 4	O	x 4

11



12



13

