












 A1	 Ø8*40	 Ø5*40	 Ø4*18	 Ø4*35
A*30	B*22	C*8	D*5	E*16
 Ø3.5*14	 G*16	 H*1	 I1	 J*2
F*100	G*16	H*1	I*4	J*2
 K*4	 L*4	 Ø20	 Ø4*16	
K*4	L*4	M*16	N*4	




1




$A1*4+B*8$

2





$A1*2+B*8+F*16+I1*4$

3




B*6

4




A2*4

5




A2*2

6




A1*8

7




A2*8


8





9



10





11



F*16+G*16


12



X4PCS


A1*16+F*4+J*2

13



$D*1+F*8+H*1$



14



X4PCS



$A2*16+D*4+E*16$

16



F*16+I2*4

15



M*16