




STAND UP

desk store

Includes one crank. Second crank shown for visualization purposes only.



Prefer video instructions?
View our video page!



Questions or concerns?
Contact us directly!



1-855-843-7920











CustomerService@StandUpDeskStore.com

standupdeskstore.com/crank-desk-assembly-videos

High Speed Dual-Point Crank Desk

PARTS INCLUDED

NOT TO SCALE

A QTY: 1	B QTY: 1	C QTY: 1	D QTY: 1	E QTY: 2
				
F QTY: 2	G QTY: 1	H QTY: 1	I QTY: 1	J QTY: 4
				
K QTY: 2	L QTY: 2	M QTY: 1*	N QTY: 1	O QTY: 1
		 Ships separate box		


HARDWARE INCLUDED

NOT TO SCALE, COLOR MAY VARY

1 QTY: 8	2 QTY: 6	3 QTY: 6	4 QTY: 22	5 QTY: 10	6 QTY: 1
M6-65 	M8-20 		M6-12 	M8-15 	M4-6 


TOOLS INCLUDED

TOOLS REQUIRED




1


A




B



A







B





6	QTY: 1
M4-6	
	


2





3





E



E




4








48" Desktop

60" Desktop




5







IF MISALIGNED:

1. Insert crank.
2. Turn crank to raise desk.
3. Raise desk until hexrod is aligned with socket.



7



8



Includes one crank. Second crank shown for visualization purposes only.

