


| Parts List | | | | |
|---|------------|------------------------------------|-----|--|
| No. | Picture | Description | Qty | |
| A | | Bench (with Folded Leg Panels) | 1 | |
| В | Ø | Support Bar | 1 | |
| Hardware | | | | |
| No. | Picture | Description | Qty | |
| с | | Bolt (M8x25mm) | 13 | |
| D | \bigcirc | Washer (M8.5/16x2mm) | 13 | |
| E | | Spanner Wrench | 1 | |
| Assembly Preparation | | | | |
| Before Beginning Assembly: | | | | |
| | | | | |
| Read instructions, cover to cover. Image: A symptotic conduction of the symptot conducticon of the symptotic conduction of the sympto | | | | |
| Assembly Steps | | | | |
| OVERVIEW Bench (A) Support Bar (B) FRONT VIEW | | | | |
| This <u>Bench</u> has multiple parts and may require up to some 15 minutes to assemble. To give you an overview of the <u>Bench</u> parts, the above picture is to help you put the various parts into perspective. Please read through the instructions here below to familiarise the parts and steps before assembly. | | | | |



Attach the Support Bar (B) to the Bench (A)

You may need to apply a little pressure to the Legs - pushing outwards, so as to enable the Support Bar (B) to be slotted into position.

A

Using Bolts (C) with Flat Washers (D), tighten the Bolts by using Spanner Wrench(E), as shown in Pic.1

Loosely tighten the Bolts, up to 80%.

| Step 4 Pic.2 D D D D D D D D D D D D D | | | |
|---|--|--|--|
| | | | |
| Secure Legs to Bench by using Bolts (C) and Flat Washers (D) with Spanner Wrench(E) as shown in Pic.2 at all 8 positions. Loosely tighten the Bolts, up to 80%. Turn it over and Sit on it. Then turn it over again, i n a sequential manner, gradually tighten each Bolt until all bolts are | | | |

evenly secured.

CAUTION: When tightening these screws, tighten sequentially.

DO NOT tighten any screw fully and then towards the next one. This would cause the frame to warp.

If there is still wobbles, loosen the screws and execute this same drop tests.

WARNING ! IF CHAIR IS NOT STABLE , IT COULD LEAD TO DAMAGING THE PRODUCT.

Step 5 You are now at the FINAL stage of this assembly. In a sequential manner, drive in and fully tighten all bolts. Thereafter, turn the Bench right way up. The Bench now is ready to be used

