










BC013

Assembly Instructions




Assembly Instructions

Ø15x12  A x 78	Ø7x38  B x 78	Ø8x30  C x 34	Ø7x48  D x 26	4MM  E x 1
103*25*12  F x 2	 G x 3	M4x10  H x 3	M4x20  I x 4	 J x 7
Ø4x40  K x 12	 L x 8	Ø4x14  M x 8	 N x 16	Ø3.5x14  O x 24
 P x 8	1356*16*20  Q x 1	M6x25  R x 4	M4x18+Ø10x10  S x 2	118*20*18  T x 4
M6x18  U x 8				62*26*2  V x 4
Ø6x30  W x 39				CL CR DL DR  x 3


STEP 1

Ax4
Bx4
Qx1
Rx4




STEP 2

Ax4
Bx4




STEP 3

Ax10
Bx10
Cx4








STEP 4

Ox4
CLx1
CRx1



STEP 5


0x8
CLx2
CRx2



x 2


STEP 6

Cx8
Dx8
Ex1




STEP 7

Ax6
Bx6
Cx2
Dx2




STEP 8




STEP 9

Wx24




STEP 10

Ax4
Bx4
Cx4
Wx9




STEP 11




STEP 12

Cx8
Dx16
Wx6




STEP 13

Ax14
Bx14




STEP 14

Ax10
Bx10




STEP 15

Nx16
Px8




STEP 16

Ax14
Bx14
Cx8




STEP 17

Lx8



STEP 18





Kx12



x 3

STEP 19



Ax12
Bx12
Ox12
DLx3
DRx3



x 3


STEP 20

Gx3
Hx3
Jx3




x 3


STEP 21





STEP 22




STEP 23



steps1






steps2



STEP 24

Sx2





FINISH