


Assembly Instructions




Storage Desk




Special Warnings

- Keep your furniture out of direct sunlight. Please use desk pads and coasters to protect the surface from dents, scratches, and moisture from hot or cold liquids.
- For cleaning, wipe the surface with a damp (not wet) cloth or wipe dry with a clean lint free cotton cloth. Window cleaning liquid or a similar cleaning liquid can be used to clean glass surface.


Operation Instructions

- Please check that all parts are present before you start the assembly of your furniture. For the protection of your furniture, place all parts on a clean and smooth surface to prevent any damage.
- Please periodically check all fitting and re-tighten as necessary.
- Please assemble the table by 2 persons or more.
- Do NOT over tighten hardware.




PART	QTY	ITEM	
A	12	M6X45	
B	20	M5X45	
C	32		
D	4	M5X55	
E	44	M3.5X14	
F	8	M4X8	

PART	QTY	ITEM	
G	2	M5X18	
H	2	M6X ϕ 28	
I	4	M8X ϕ 50	
J	4		
K	2		
L	1		




6X45mm 5X45mm bolt installation as below




1

.SCREWS		.SCREWS	
I	M8X ϕ 50 4 PCS	A	M6X45 4 PCS





2





3

.SCREWS		.SCREWS	
D	M5X55 4 PCS	C	M5X45 4 PCS



4

.SCREWS	
B	M5X45 4 PCS





5

.SCREWS

C



2 PCS





6

.SCREWS

C



2 PCS



7

.SCREWS

C



2 PCS



.SCREWS



B



M5X45



2 PCS



8

.SCREWS

C



4 PCS



.SCREWS



B



M5X45





4 PCS





9

.SCREWS		.SCREWS	
C	2 PCS	B	M5X45
			



10



.SCREWS		.SCREWS	
C	4 PCS	B	M5X45
			



11

.SCREWS		.SCREWS	
C	6 PCS	B	M5X45
			



.SCREWS	
A	M6X45
	



12


.SCREWS		.SCREWS	
C	6 PCS	B	M5X45
			

.SCREWS	
A	M6X45
	




13

.SCREWS		.SCREWS	
F	M4X8 8 PCS	H	M6xφ28 2 PCS
		.SCREWS	
		J	4 PCS




14

.SCREWS	
E	M3.5X14 4 PCS




15

.SCREWS	
E	M3.5X14 4 PCS




16

.SCREWS		.SCREWS	
G	M5X18 2 PCS	E	M3.5X14 18 PCS
		.SCREWS	
		K	2 PCS




17



.SCREWS

E M3.5X14
9 PCS

18



.SCREWS

E M3.5X14
9 PCS

19

