


















ASSEMBLY INSTRUCTION




1





2




3





A1  Ø12x10mm
x 3


C1  Ø6 x 30mm
x 6




4







A1  Ø12x10mm
x 1


C1  Ø6 x 30mm
x 2






5





A1  $\varnothing 12 \times 10 \text{mm}$
x 1

C1  $\varnothing 6 \times 30 \text{mm}$
x 2


6





A1  $\varnothing 12 \times 10 \text{mm}$
x 4



C1  $\varnothing 6 \times 30 \text{mm}$
x 4

7




8






<p>A1</p>  <p>Ø12x10mm</p> <p>x 8</p>	<p>C1</p>  <p>Ø6 x 30mm</p> <p>x8</p>
--	--


9



10







A1 
Ø12x10mm
x 8

C1 
Ø6 x 30mm
x 8


11


x2




<p>D2</p>  <p>x4</p>	<p>E</p>  <p>M4 x 25mm</p> <p>x8</p>	<p>A1</p>  <p>Ø12x10mm</p> <p>x 8</p>
--	---	---


12




<p>J</p>  <p>x2</p>
--




13



E5  M3x 16mm
x6

N  x6

14



Carton	Reference No.	Quantity
1/1	1	1
1/1	2	1
1/1	3	1
1/1	4	1
1/1	5	1
1/1	6	1
1/1	7	3
1/1	8	1
1/1	9	1
1/1	10	2
1/1	11	2
1/1	12	2
1/1	13	2
1/1	14	2
1/1	16	1
1/1	17	2
1/1	18	1
1/1	ACCESSORIES	1