





USER'S MANUAL








Hardware


A M6x30mm

 4PCS


B M8x70mm

 4PCS


C M8

 8PCS


D $\phi 6$

 4PCS


E $\phi 8$

 4PCS





F $\phi 8$

 12PCS



G M8x40mm

 4PCS

H M6x20mm

 4PCS


 2PCS


 1PC

 M6x30mm	
A	4PCS
 M6x20mm	
H	4PCS
 Ø6	
D	4PCS
	





M8x70mm

B 4PCS



Ø8

E 4PCS





Ø8


F 4PCS



M8

C 4PCS





M8x40mm

G 4PCS



ø8

F 8PCS



M8

C 4PCS

