



ASSEMBLY INSTRUCTION


type1




type2




type3

















type4





(A)	x 18	(B)	x 26	(C)	x 22	(D)	x 8	(E)	x 10	(F)	x 2
											
M6x40		M6x30		M6x12		M7x50		M6x15			
(G)	x 4	(H)	x 1	(I)	x 3						
											
		M4									

① x1PC 	② x1PC 	③ x1PC 
④ x2PCS 	⑤ x2PCS 	⑥ x1PC 
⑦ x1PC 	⑧ x2PCS 	⑨ x1PC 
⑩ x1PC 	⑪ x1PC 	⑫ x1PC 
⑬ x4PCS 	⑭ x1PC 	⑮ x1PC 
⑯ x4PCS 	⑰ x2PCS 	

1

(E)

x 10

M6x15

2

(A)

x 10


(H)

x 1

M6x40



M4

3




(B)	x 8	(H)	x 1
 M6x30		 M4	

4




(D)	x 8	(H)	x 1
 M7x50		 M4	

5




(A)	x 4	(C)	x 3	(H)	x 1
					
M6x40		M6x12		M4	

6




(A)	x 4	(C)	x 3	(H)	x 1
					
M6x40		M6x12		M4	

7




(B)	x 18	(H)	x 1
M6x30		M4	

8




(C)	x 6	(H)	x 1
M6x12		M4	

9



(F)	x 2	(G)	x 1	(C)	x 6	(H)	x 1
							
				M6x12		M4	

10



(I)	x 3
	

1

type2

(E) x 10

M6x15

2


(A) x 10

M6x40

(H) x 1


M4

3




(B)	x 8	(H)	x 1
 M6x30		 M4	

4




(D)	x 8	(H)	x 1
 M7x50		 M4	

5




(A)	x 4	(C)	x 3	(H)	x 1
					
M6x40		M6x12		M4	

6




(A)	x 4	(C)	x 3	(H)	x 1
					
M6x40		M6x12		M4	

7




(B)	x 18	(H)	x 1
			
M6x30		M4	


8




(C)	x 6	(H)	x 1
			
M6x12		M4	

9



(F)	x 1	(G)	x 3	(C)	x 8	(H)	x 1
							
				M6x12		M4	



10



(I)	x 3
	



1

type3




(E)	x 10
 M6x15	

2




(A)	x 10	(H)	x 1
 M6x40		 M4	

3




(B)	x 8	(H)	x 1
			
M6x30		M4	

4




(D)	x 8	(H)	x 1
			
M7x50		M4	

5




(A)	x 4	(C)	x 3	(H)	x 1
					
M6x40		M6x12		M4	

6




(A)	x 3	(C)	x 4	(H)	x 1
					
M6x40		M6x12		M4	

7




(B)	x 18	(H)	x 1
			
M6x30		M4	

8




(C)	x 6	(H)	x 1
			
M6x12		M4	

9



(G)	x 4	(C)	x 8	(H)	x 1
					
		M6x12		M4	



10



(I)	x 3
	



1

type4




(E)	x 10
 M6x15	

2





(A)	x 10	(H)	x 1
 M6x40		 M4	

3




(B)	x 8	(H)	x 1
 M6x30		 M4	

4




(D)	x 8	(H)	x 1
 M7x50		 M4	

5




(A)	x 4	(C)	x 3	(H)	x 1
					
M6x40		M6x12		M4	

6




(A)	x 3	(C)	x 4	(H)	x 1
					
M6x40		M6x12		M4	

7




(B)	x 18	(H)	x 1
			
M6x30		M4	

8




(C)	x 6	(H)	x 1
			
M6x12		M4	

9



(F)	x 1	(G)	x 4	(C)	x 10	(H)	x 1
				M6x12		M4	

10



(I)	x 3