

Assembly Instructions



For the most current instructions, additional assembly tips, to report damage or request parts, please visit our website

Parts List




Parts List


Α		Ø16*2mm	Sponge pad	4	pcs
В	(a)	Ø6*15mm	Bolt	16	pcs
С		M4mm	Wrench	1	рс

The hardware quantities listed above are required for proper assembly. Some extra hardware may also have been included.





Stick the sponge pad (A) to the metal leg (2) as per diagram.



Use wrench (C), bolt (B) to secure the metal leg (2) to the table top (1).

