






















ASSEMBLY INSTRUCTIONS








Part List

			
① x2pcs	② x2pcs	③ x1pc	④ x2pcs
			
⑤ x2pcs	⑥ x1pc	⑦ x1pc	⑧ x1pc
			
⑨ x1pc	⑩ x1pc	⑪ x1pc	⑫ x2pcs
			
⑬ x1pc	⑭ x1pc	⑮ x2pcs	⑯ x2pcs
			
⑰ x2pcs	⑱ x2pcs		

Hardware List

				 Ø3.5x12mm
Ⓐ x2pcs	Ⓑ x2pcs	Ⓒ x2pcs	Ⓓ x2pcs	Ⓔ x16pcs
 Ø4x35mm	 M6x25mm	 M6x35mm	 M6x14	 Ø7x40mm
Ⓕ x8pcs	Ⓖ x36pcs	Ⓗ x8pcs	Ⓙ x8pcs	⓫ x6pcs
 Ø6x35mm	 Ø15x12mm	 Ø15x10mm	 Ø8x30mm	 ⓪ x2pcs
Ⓚ x14pcs	Ⓛ x6pcs	Ⓜ x8pcs	Ⓝ x12pcs	
 M4x10mm	 Ⓚ x4pcs	 4x35mm	 Φ6x30mm	 Ⓣ x2pcs
Ⓟ x4pcs	Ⓠ x4pcs	Ⓡ x2pcs	Ⓢ x2pcs	
 Ⓡ x2pcs				

Step 1




(A) × 1pc




Ø3.5x12mm

(E) × 2pcs



Step 2




(B) × 1pc





Ø3.5x12mm

(E) × 2pcs




Step 3


		
Ⓐ×1pc	Ⓑ×1pc	Ⓔ×4pcs Ø3.5x12mm




Step 4




Step 5




Step 6




Step 7




Step 8



Step 9



Step 10



M6x25mm


Ⓔ × 14 pcs



M6x35mm

Ⓕ × 4 pcs

Step 11



M6x25mm


Ⓔ × 14 pcs



M6x35mm

Ⓕ × 4 pcs

Step 12



M6x25mm



Ⓔ × 8 pcs



M6x14


Ⓘ × 8 pcs

Step 13



Ø6x35mm

Ⓚ × 8 pcs




Step 14




Ø15x10mm

Ⓜ ×8pcs



Step 15




Step 16




Ø4x35mm


Ⓕ×8pcs



Step 17



Ⓒ×2pcs




Ⓓ×2pcs




Ø3.5x12mm

Ⓔ×8pcs




Step 18

	 M4x10mm
⓪ × 2 pcs	Ⓟ × 4 pcs



Step 19



Step 20

4x35mm

Ⓡ×2pcs

Φ6x30mm

Ⓢ×2pcs



Ⓣ×2pcs

