

Assembly instructions for the sofa, including tool requirements, time, and personnel.


Tools: A screwdriver is shown as the required tool. A power drill is shown with a diagonal line through it, indicating it is not required.

Warning: A warning triangle with an exclamation mark is present.


Time: A clock icon is shown, with the text "30'" below it, indicating the estimated assembly time is 30 minutes.

Personnel: A person icon is shown, with the text "2" below it, indicating that two people are required for assembly.


1 x 4




2



3




6 x 2





2


4




9



5




7




8

A



x 16


B



M4
x
70


x 6

1




x 4

2




x 2

3




x 1

4




x 1

5




x 1

6




x 2

7




x 1

8



x 1


9



x 1


1

4



x1

5





x1

A




x6

4



5




2

3




x1

3




5



1a




1b





3





4





5





5



6





7




8

B
M4
x
70
x 3



9

7





x 1

A



x 4






10



6





x 1



11



12



!

