


EN_ IMPORTANT, RETAIN FOR FUTURE REFERENCE: READ CAREFULLY.













FR_ IMPORTANT: A LIRE ATTENTIVEMENT ET À CONSERVER POUR CONSULTATION ULTÉRIEURE.

ES_ IMPORTANTE, LEA Y GUARDE PARA FUTURAS REFERENCIAS.



DE_ „WICHTIG! SORGFÄLTIG LESEN UND FÜR SPÄTER NACHSCHLAGEN AUFBEWAHREN.“

IT_ IMPORTANTE! CONSERVARE IL PRESENTE MANUALE PER FUTURO RIFERIMENTO E LEGGERLO ATTENTAMENTE.

PARTS

 ① x01	 ② x02	 ③ x01
 ④ x01	 ⑤ x01	 ⑥ x01
 ⑦ x01	 ⑧ x01	 ⑨ x02
 ⑩ x02	 ⑪ x01	 ⑫ x04


HARDWARE

 A x08 M8*35	 B x06 M8*55	 C x10 M6*30
 D x06 M6*50	 E x08 M6*55	 F x04 M6*55
 G x06	 H x01 M4	 I x01 M5


① x 1




③ x 1




D x 6




④ x 1




⑤ x 1




⑥ x 1




⑦ x 1




A x 8




⑧ x 1




⑨ x 1



Ⓑ x 4





⑩ x 2




Ⓒ x 2




Ⓓ x 6




⑨ x 1




Ⓑ x 2




⑪ x 1




Ⓕ x 4




⑫ x 4



E x 8



② x 2



C x 8

