


ASSEMBLY INSTRUCTION


PART LIST

DO NOT FULLY TIGHTEN SCREWS AND NUTS UNTIL THE ENTIRE ITEM IS COMPLETELY ASSEMBLED

A-TOP X 1



B-LEG X 2





C-CONNECT X 1




Item	List of Hardware	Q.ty
①	Bolt 8 X 35 	8
②	Bolt 8 X 50 	2
③	Lock washer 	10
④	Flat washer 	10
⑤	Wooden 	10
⑥	Allen key 	1

Step 1



Step 2



Step 3

