


# Assembly Instruction Sheet Folding 4-Tier Corner Shelf



## LIST OF PARTS



Snap on Mantel Top  
1 PC

## LIST OF HARDWARE



Front Support  
MS0952V  
1 PC



Screw F6 x 1 1/4"  
RF10002  
1 PC


## Anti-Tipping



Screw P6 x 5/8"  
RF10080  
2 pcs.



Screw P6 x 1 1/4"  
RF10103  
2 pcs.



Metal Plate  
RF40214  
2 pcs.




Diagram 1.

1. Open the left panel and right side panel of corner shelf as shown in Diagram 1.




Diagram 2.


2. Put the front support (MS0952V) into the hole under the Bottom shelf as per Diagram 2.

(A) Snap on Mantel Top

Align the hole's mantel top to meet the pins before press down to "click" locked.

Diagram 3.

Use screw (RF10002) through predrilled hole



## Anti-Tipping

Use metal plate (RF40214) and screws P6 x 5/8" (RF10080) to attach two side panels thru the studs into the wall, using screws P6 x 1 1/4" (RF10103) as per Diag. 4.




Diagram 4.

*"It is dangerous to stack two units one on top of the other. The small base isn't stable enough for such combination."*