





ASSEMBLY INSTRUCTION

SKU:WF321527
SKU:WF321528



ASSEMBLU INSTRUCTION



Parts List For WF321528

①




X2

③




X2

④




X2

⑥




X4

⑦




X2

⑧




X2

②③




X3

②④




X3

②⑤



X3

②⑥












X3

②⑦










X12


Parts List For WF321527

②  X2	⑤  X1
⑨  X2	⑩  X1
⑪  X10	⑫  X1
⑬  X1	⑭  X2
⑮  X1	⑯  X1
⑰  X1	⑱  X2
⑲  X3	⑳  X3
㉑  X1	㉒  X2

Parts List For WF321528


(A)  M8x60mm x6	(B)  M8x50mm x4	(C)  M8x40mm x8	(D)  M8x35mm x10
(E)  M8x20mm x8	(F)  M6x12mm x35	(G)  M6x30mm x3	(H)  M6x35mm x8
(I)  M3x12mm x2	(J)  M8x16mm x3	(K)  Ø17*Ø8.5*2 x9	(L)  M6 x6
(M)  M4 x1	(N)  M5 x1	(O)  x1	(P)  X1
(Q)  x20	(R)  x20	(S)  x12	
(T)  (T1)  x24 x4	(U)  X1	(V)  x2 V1  x4 V2  x10 V3  x2 V4  x2	

1




	Q × 10
	P × 1

2




	Q × 10
	P × 1

3





	(T) x4
	(P) x1

4





	(T2) x4
	(T1) x16
	(P) x1

5




	(V2) x2
	(V4) x1
	(T3) x2
	(T1) x4
	(P) x1

6



	(V2) x2
	(V4) x1
	(T3) x2
	(T1) x4
	(P) x1


7



x2


	V2 x6
	V3 x2
	P x1

8




	R x10
	P x1

9





10





	(R) x10
	(P) x1

11





	I x2
	P x1
	U x1

12





	H x4
	M x1

13





	(H) x4
	(M) x1

14





	(C) x4
	(N) x1

15





	Ⓒ G x3
	Ⓒ M x1

16






	Ⓒ C x2
	Ⓒ N x1

17





	(C) x2
	(N) x1

18





	(F) x6
	(M) x1

19





	(F) x8
	(M) x1

20




21





	(P) x1
--	--------

22




	(V) x1
	(V1) x2

23






	(P) x1
--	--------

24






	(V) x1
	(V1) x2

25




	(B) x4
	(N) x1

26




	(E) x4
	(N) x1



27



28





29





	(D) x4
	(N) x1



30



	(A) x4
	(K) x4
	(N) x1




33



X3

	(F) X6
	(L) X6
	(M) X1
	(O) X1



34



X3



	(S) X12
--	---------

35




	(F) X15
	(M) X1

36



	(J) X3
	(K) X3
	(N) X1

37



38

